



CONCENTRATION OF ADA RAMPS THROUGHOUT HARRISONBURG

ADA RAMP ACCESSIBILITY CONDITION THROUGHOUT HARRISONBURG

Grade	Ramp Width	Detectable Warning Surface	Material Condition
A <small>(rated only if all listed conditions exist)</small>	48" or greater	Truncated Dome	<u>Fair or Better Condition</u> Limited or tight cracking, faulting (<1/4"), isolated spalling
B <small>(maximum rating if any of the listed condition exists)</small>	>36" to <48"	Exposed Aggregate Surface	<u>Poor Condition</u> Moderate cracking, faulting (1/4"-3/4"), moderate spalling
C <small>(maximum rating if any of the listed condition exists)</small>	36" or less	No detectable warning surface	<u>Very Poor Condition</u> Severe cracking, faulting (>3/4"), extensive spalling
D	A curb ramp is needed but does not exist at the location to access an existing sidewalk where it crosses a curb.		
N/A	A curb ramp is NOT needed at the location (typically because either a sidewalk does not exist or there is no curb at this location).		



*Note that it takes only one of the column attributes from lower (more severe) in the table to be present for any given sidewalk to be classified as the more severe category.