ADA TRANSITION PLAN

IMPEDIMENTS IF YOU OBSERVE AN ISSUE CAUSED BY AN IMPEDIMENT CALL HARRISONBURG PUBLIC WORKS AT 540-434-5928

IMPEDIMENT EXAMPLES




NARROW SIDEWALK


Grade Breaks & Changes in Level

R302.6.1 Grade breaks must be flush R302.6.2 Changes in level (Referred to in the NPRM as R302.7.2 Vertical Surface

Discontinuities

Changes in level can be up to ¼" without treatment or ½" if beveled with a slope no steeper than 1:20 (5.0%).






GRAPHICS FROM THE UNITED STATES ACCESS BOARD

OBSTRUCTION EXAMPLES






IMPROPER PLACEMENT OF SIDEWALK PLANTERS/VEGETATION

IMPROPER PLACEMENT OF SANDWICH BOARDS

Horizontal Openings

- Horizontal openings in ground surfaces, such as those in gratings and joints, other than flangeway gaps should not allow passage of a sphere larger than $\frac{1}{2}$ " in diameter.
- Where multiple directions of travel intersect, elongated openings are permitted but must be placed so that the long dimension is perpendicular to the dominant direction of travel.







IMPROPER PLACEMENT **OF TRASH TOTERS**



IMPROPER PLACEMENT OF E-SCOOTER (BIRD)



SNOW REMOVAL CITY CODE SECTION 6-1-15 BUSINESS

• WITHIN 24 HOURS IF SNOWFALL IS SIX INCHES OR LESS. • WITHIN 36 HOURS IF SNOWFALL IS GREATER THAN SIX INCHES.

WWW.HARRISONBURGVA.GOV/SNOW-PLOW

RESIDENTS, BUSINESS OWNERS, AND PROPERTY OWNERS MUST CLEAR SNOW FROM THE SIDEWALK IN FRONT OF THEIR HOME OR



CROSS SLOPE







